

附件3

图1



图2



图3



图4



图5



图6



图7



图8



图9



图10



图11



图12



图13



图14



图15



图16



图17



图19



图18



图20



图21



图23



图22



图24



图25



图26



图27



图28



图29



图30



图31



图32



图33



图34



图35



图36



图37



图38



图39



图40



图41



图42



图43



图44



图45



图46



图47



图48



图49



图50



图51



图52





图53



图54



图55



图56



图57



3栋2楼3楼铁窗喷漆

图59

图58



3栋1楼
爆钢筋

图60



3栋后门刮补腻子

图61



3栋1楼 瓷砖脱落

图62



3栋1楼 瓷砖开裂

图63



3#1
103门前天花漏水

图64



3栋1楼
106门口外墙面脱落



3栋303刮腻子

图65



图66



图67



图68



图69



图70



图71



图72



图73



图74



图75



图76



图77



图78



图79



图80



图81



图82



图83



图84



图85



图86



图87



图88



图89



图90



图91



图92



图93



图94



图95



图96



图97



图98



图99




图100



图101



图102



图103



图104



图105



图107



图109



图111



图113



图106




图108



图110



图112



图114



图115



图116



图117



图118



图119



图120




图121



图122



图123



图124




图125



图126



图127



图128



图129



图130



图131



图132



图133



图134



图135



图137



图139



图141



图143



图136



图138



图140



图142



图144



图145



图146



图147



图148



图149



图150



图151



图152



图153



图154



图155



图156



图157



图158



图159



图160



图161



图162



图163



图164



图165



图166



图167



图168



图169



图170



图171



图172



图173

